



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III3district.htm](http://emnrd.state.nm.us/ocd/District%20III3district.htm)

OIL CONS. DIV DIST. 3

JUN 21 2017

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-21-17 Operator Burlington Res API #30-0 45-11294

Property Name Allison Ut Well No. 17 Location: Unit 24 Section 32 Township 32 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 210 Intermediate 0 Casing 218 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	218	0	219
10 min	0	0	218	0	219
15 min	0	0	218	0	219
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		✓
Nothing	✓	
Gas		✓
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

SH- Nothing when opened Nothing when
opened after 5 min shut in Int- light blow through 1/4" valve
House app not being used- light blow at 5 min checked corner

By [Signature]

Witness Monica Gutierrez

(Position)

Nothing when opened after 5 min
shut in

E-mail address _____