



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III3district.htm](http://emnrd.state.nm.us/ocd/District%20III3district.htm)

OIL CONS. DIV DIST. 3

JUN 21 2017

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-21-17 Operator ConocoPhillips API #30-0 45-11298
Property Name Sunyan 32-714 Well No. 39 Location: Unit DK255 Section 23 Township 32 Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing 10099 Intermediate 101 Casing 101 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	101	101	8	96
10 min	0	101	101	2.8	94
15 min	0	101	101	2.7	93
20 min				2	92
25 min				2	90
30 min				2	89

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		✓
Surges		
Down to Nothing		
Nothing	✓	
Gas		✓
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD

INTERMEDIATE 35

REMARKS:

BH nothing when opened - nothing when
opened after 5 min shut in - Int. had blow full. 30
day completion - PK in hole mud dropped with casing

By Frank Amador

Witness Maria Kuehling PK did not drop

(Position)

E-mail address _____

Gas analysis all strings - well bore
Schematic just turned in in last
3 years