



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 24-JUNE-2017 Operator LOPELO API #30-0 45-28988

Property Name SAN JUAN 32-1 Well No. 114 Location: Unit ___ Section 17 Township 31 Range 9

Well Status(Shut-In or Producing) Initial PSI: Tubing 105 Intermediate 0 Casing 107 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	108	0	109
10 min	0	0	108	0	109
15 min	0	0	109	0	109
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	X
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ___ FRESH ___ SALTY ___ SULFUR ___ BLACK ___

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS: OPENED THE BRADENHEAD AND NOTHING CAME OUT
OPENED THE INTERMEDIATE AND NOTHING CAME OUT

By [Signature]

Witness [Signature]

(Position)

E-mail address _____

OIL CONS. DIV DIST. 3
JUN 27 2017