



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3

JUN 21 2017

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-21-17 Operator ConocoPhillips API #30-0 45-32501
Property Name San Juan 32-7 lot Well No. 446 Location: Unit Section 22 Township 32 Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing 129 Intermediate 0 Casing 136 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead Int	Csg	INTERM Int	Csg
TIME					
5 min					
10 min					
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE

REMARKS:

What Calling BH dead at 30 seconds
need to dig - I'll find another valve
up to 2 feet.

By Frank Amador

Witness Monica Kuehling

(Position)

E-mail address