



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3

JUL 12 2017

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-12-17 Operator Conce Phillips API #30-0 39-23020
Property Name San Juan 31-b-14 Well No. 8A Location: Unit 6 Section 6 Township 30 Range 6
Well Status (Shut-In or Producing) Initial PSI: Tubing 67 Intermediate 11A Casing 67 Bradenhead 10

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead			Int	Csg
	BH	Int	Csg		
TIME					
5 min	0		68		
10 min	0		69		
15 min	0		69		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 11A

REMARKS:

Shut to dead at 2 seconds. - Nothing after
5 min shut in
Free flowing - by lake.
By MSO (Position)
Witness Mona Kullberg

E-mail address _____