



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District II/3district.htm](http://emnr.state.nm.us/ocd/District%20II/3district.htm)

OIL CONS. DIV DIST. 3

JUL 12 2017

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-12-17 Operator Concepcion Phillips API #30-0 39-26077
Property Name San Juan 3H Ltd Well No. 37 Location: Unit 9 Section 6 Township 30 Range 6
Well Status (Shut-In or Producing) Initial PSI: Tubing 126 Intermediate 0 Casing 125 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	126	0	128
10 min	0	0	126	0	128
15 min	0	0	127	0	128
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	/	/
Nothing		
Gas	/	/
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

Small puff when opened - Nothing when opened
after 5 min shut-in - Int. Puff when opened
sets by lake Nothing when opened after 5 min shut in

By Rahil Reddy

Witness Monica Gutierrez

MSO

(Position)

E-mail address _____