



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

02H

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-7-17 Operator Encana Oil & Gas API #30-0 43-21196

Property Name North Alamita Unit Well No. 322H Location: Unit E Section 33 Township 23N Range 2W

Well Status (Shut-In or Producing) Initial PSI: Tubing 95 Intermediate N/A Casing 124 Bradenhead 9

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing TIME	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min	<u>9</u>	<u>N-A</u>	<u>126</u>		
10 min	<u>9</u>		<u>124</u>	<u>N/A</u>	
15 min	<u>9</u>		<u>124</u>		
20 min	<u>9</u>		<u>124</u>		
25 min	<u>9</u>		<u>124</u>		
30 min	<u>9</u>	<u>N-A</u>	<u>124</u>		

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 9

INTERMEDIATE N/A

REMARKS:

Previous Name Lybrook E 33 02H - running piston, Left BH shut

By Arthur Sullivan

Witness _____

Lead Tech
(Position)

OIL CONS. DIV DIST. 3

JUL 10 2017

E-mail address arthur.sullivan@encana.com