



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III3distric.htm](http://emnrd.state.nm.us/ocd/District%20III3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-6-17 Operator Encana Oil & Gas API #30-0 43-21198

Property Name North Alamito Unit Well No. 328 H Location: Unit P Section 32 Township 23N Range 7W

Well Status (Shut-In or Producing) Initial PSI: Tubing 40 Intermediate N/A Casing 138 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>N/A</u>	<u>138</u>		
10 min	<u>0</u>	<u>1</u>	<u>140</u>	<u>N/A</u>	
15 min	<u>0</u>		<u>138</u>		
20 min	<u>0</u>		<u>136</u>		
25 min	<u>0</u>		<u>141</u>		
30 min	<u>0</u>	<u>N/A</u>	<u>140</u>		

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Previous Name Lybrook P-32 - Plunger running - Left BH shut

By Arthur Sullivan

Witness _____

OIL CONS. DIV DIST. 3

JUL 10 2017

(Position)

E-mail address: arthur.sullivan@encana.com