



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emmr.state.nm.us/ocd/District III/district.htm](http://emmr.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 18 JULY-2017 Operator ENCANA API #30-0 43-21-22C

Property Name VENADO CANYON Well No. 103H Location: Unit 32 Section 32 Township 22 Range 6

Well Status (Shut-In or Producing) Initial PSI: Tubing 52 Intermediate N/A Casing 26 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM		
	BH	Bradenhead Int	Csg	Int	Csg	
TIME						
5 min	0	N/A	121			
10 min	0	1	126			
15 min	0	5	126			
20 min						
25 min						
30 min						

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	X	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS: OPENED THE BRADENHEAD AND NOTHING CAME OUT

By Mary Thib
operator
(Position)

Witness JEFFREY

E-mail address greg.stock@encana.com

OIL CONS. DIV DIST. 3
JUL 17 2017