



**OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distrct.htm](http://emnrd.state.nm.us/ocd/District%20III/3distrct.htm)**

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Well Status(Shut-In or Producing) Initial PSI: Tubing 64 Intermediate ✓ 19 Casing 194 Bradenhead 16

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE					
Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		194		
10 min	0		194		
15 min	0		194		
20 min	0		194		
25 min	0		194		
30 min	0		194		

FLOW CHARACTERISTICS	
BRADENHEAD INTERMEDIATE	
Steady Flow	/
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	/

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD

INTERMEDIATE

REMARKS:

REMARKS: Spent out 1 cup water to clear gussie with
sprouts of water for full 30 min test.
Water analysis taken - 15.15

By [Signature]

Witness

(Position)

E-mail address _____