



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-11-2017 Operator Encarna oil & Gas API #30-0 43 - 21127
Property Name Lybrook Well No. 014 Location: Unit A Section 32 Township 23N Range 6W
Well Status (Shut-In or Producing) Initial PSI: Tubing 29 Intermediate N/A Casing 116 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

1210

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>N/A</u>	<u>117</u>		
10 min	<u>0</u>	<u>N/A</u>	<u>119</u>		
15 min	<u>0</u>	<u>N/A</u>	<u>117</u>	<u>N/A</u>	
20 min	<u>0</u>	<u>N/A</u>	<u>117</u>		
25 min	<u>0</u>	<u>N/A</u>	<u>117</u>		
30 min	<u>0</u>	<u>N/A</u>	<u>117</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	<u>N/A</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Plunger Running - Left BH Shut in

By Mary Stock
Operator
(Position)

Witness _____

OIL CONS. DIV DIST. 3

E-mail address greg.stock@encarna.com

JUL 14 2017