



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-12-17 Operator: Enervest Operating, LLC API # 30-039-22296

Property Name: Jicarilla C Well No. 1E Location: Unit: G Section: 23 Township: 26N Range: 5W

Well Status(Shut-In or Producing) Initial PSI: Tubing 78 Intermediate Casing 129 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>Ø</u>		<u>124</u>		
10 min	<u>Ø</u>		<u>124</u>		
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>✓</u>
Nothing	
Gas	
Gas & Water	
Water	

OIL CONS. DIV DIST. 3

MAY 24 2017

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE

REMARKS: Well blew dead after 2 seconds

By Robert Canty
Operator
(Position)

Witness

E-mail address