

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

JUL 14 2017

FORM APPROVED
OMB No. 1004-0137
Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

Farmington Field Office
Bureau of Land Management

5. Lease Serial No.
80G13121809
6. Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator
WPX Energy Production, LLC

3a. Address
PO Box 640 Aztec, NM 87410

3b. Phone No. (include area code)
505-333-1816

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
SHL: 1918' FSL & 1267' FEL SEC 10 22N 7W
BHL: 1156' FNL & 2291' FWL SEC 14 22N 7W

7. If Unit of CA/Agreement, Name and/or No.
NMNM135217A

8. Well Name and No.
N ESCAVADA UNIT #328H

9. API Well No.
30-043-21286

10. Field and Pool or Exploratory Area
ESCAVADA N, MANCOS

11. Country or Parish, State
Sandoval, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Hydraulic Fracturing	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	<u>Intermediate</u>
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	<u>Casing</u>

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

7/9/17 - MIRU-"Psi Test W/ Antelope Services: Shell Test High 2,000 Psi for 30 Min: Well Head Connection, 9 5/8 Surface Casing, Blind Rams, Kill Valves, Relief side Valves, Stinger flex hose, All outer Valves in Choke Manifold, 7" Casing String Low 250 psi for 5 Min: Well Head Connection, 9 5/8 Surface Casing, Blind Rams, Kill Valves, Relief side Valves, Stinger flex hose, All outer Valves in Choke Manifold, all tested good and recorded on chart"

7/10/17-Drilling ahead 8-3/4" Intermediate Hole.

7/11/17-TD 8-3/4" intermediate hole @ 5810' (5063' TVD').

Ran Intermediate Casing 7", 137 jts of 23# J-55, LT&C 1- 20' pup jt, set @ 5,802' MD. FC @ 5758'. Test secondary seal 1500 psi, good test Cement with Halliburton. 5,200 Psi Test on Lines Fresh Water Spacer @ 8.3# {10 Bbls }, followed by Chem Wash @ 8.4# {30 Bbls }, followed by Fresh Water Spacer @ 8.3# {10 Bbls }, followed by Lead Cement @ 12.3# { 475 sks/165 Bbls HALCEM * } followed by Tail Cement @ 13.5# { 500 sks/115.8 Bbls of VARICEM * } Drop wiper plug, Displace, (Calculated 226 bbls) After 150 bbls gone, by pass chem wash to blow tank after 170 bbls gone, press climbing w/ intermittent circ, slow rate down t/ 3 bpm, lost returns, slow rate down to 2 bpm, jam locked up w/ 205 bbls gone. 3700 psi. shut down. @ 11:59 7/11/2017 check floats (held ok), no cement to surface.

7/12/17- Notified BLM/ODD

7/13/17-Ran CBL- TOC @ 480'

NOTE: WPX will MI to Install & test BOP and 7" casing at later date. Will file on Final Casing Sundry. ✓

ACCEPTED FOR RECORD

JUL 14 2017

FARMINGTON FIELD OFFICE
BY:

OIL CONS. DIV DIST. 3

JUL 19 2017

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

Lacey Granillo

Title Permit Tech III

Signature

Date 7/13/17

THE SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

NMOCDA