



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

AUG 08 2017

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8/8/2017 Operator Dugan API #30-0 45-05580

Property Name West Bisti Unit Well No. 160 Location: Unit C Section 1 Township 25 Range 13

Well Status (Shut-In or Producing) Initial PSI: Tubing 35 Intermediate NA Casing 35 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	NA	35		
10 min	0		35		
15 min	0		35		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	X	
Nothing		
Gas	X	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0psi INTERMEDIATE _____

REMARKS:

Slight puff to nothing in one second. Nothing on BH after five min shut in.

By Kelly L. Hall
Prod. Foreman
(Position)

Witness [Signature]

E-mail address _____