



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3

AUG 09 2017

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-9-17 Operator 3P America API #30-0 45-28553
Property Name NEBA Middle Mesa SW Well No. 2 Location: Unit M Section 11 Township 31 Range 7
Well Status(Shut-In or Producing) Initial PSI: Tubing 1281 Intermediate 0 Casing -10 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>0</u>	<u>-10</u>	<u>0</u>	<u>-10</u>
10 min	<u>0</u>	<u>0</u>	<u>-10</u>	<u>0</u>	<u>-10</u>
15 min	<u>0</u>	<u>0</u>	<u>-10</u>	<u>0</u>	<u>-10</u>
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>✓</u>
Nothing	
Gas	<u>✓</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

3P light blow to clear in 25 seconds. +uff when
opened after 5 min shut in Int. Not light blow to clear
at 3:55 0 Nothing when opened after 5 min. Shut in

By Eugenia Hamilton
Lead Tech.
(Position)

Witness Morgan Kuehling

E-mail address _____