

**NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT**

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

OIL CONS. DIV DIST. 3
AUG 09 2017

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	7.14.17	Operator	BP America Production Company	API #	3004532491
---------------------	---------	-----------------	-------------------------------	--------------	------------

Property Name BARNES LS 007M-MV/DK **Location:** Unit E Section 23 Township 32 Range 11
 (Well Name and Number)

Pressure (Shut-in or Producing) _____ Tubing 16.4 Intermediate 265.8 Casing 81.8 Bradenhead 105.8

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	0.1	80.8	265.8	229.0	79.5	Steady Flow	12 sec	stayed steady
10 minutes	0.1	80.5	265.9	204.1	81.6	Surges		
15 minutes	0.1	80.3	266.0	177.4	82.5	Down to Nothing	26 sec to 0.1	
20 minutes	0.1	80.0	266.1	177.4	83.1	No Flow		
25 minutes	0.1	79.1	266.2	177.4	83.5	Gas		
30 minutes	0.1	79.8	266.3	177.4	83.8	Gas and Water		
5 minute SI						Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 683 Intermediate 226

REMARKS:

REMARKS: Took gas samples from Bradenhead, Intermediate, Casing, & Tubing. Intermediate Blow down was $\frac{1}{2}$ " needle valve

By Eugenia Hami Hon Witness _____
Lead Tech.

 (Position)