



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

## MECHANICAL INTEGRITY TEST REPORT (TA OR UIC)

Date of Test 8-24-2017 Operator Hilcorp Energy API # 30-0 45-11411

Property Name Allison Unit Well # 1 Location: Unit E Sec 17 Twn 32 Rge 6

Land Type:

State \_\_\_\_\_  
Federal \_\_\_\_\_  
Private X \_\_\_\_\_  
Indian \_\_\_\_\_

OIL CONS. DIV DIST. 3  
AUG 24 2017

Well Type:

Water Injection \_\_\_\_\_  
Salt Water Disposal \_\_\_\_\_  
Gas Injection \_\_\_\_\_  
Producing Oil/Gas \_\_\_\_\_  
Pressure observation X \_\_\_\_\_

Temporarily Abandoned Well (Y/N): N TA Expires: \_\_\_\_\_

Casing Pres. Ø \_\_\_\_\_  
Bradenhead Pres. Ø \_\_\_\_\_  
Tubing Pres. Ø \_\_\_\_\_  
Int. Casing Pres. \_\_\_\_\_

Tbg. SI Pres. \_\_\_\_\_ Max. Inj. Pres. \_\_\_\_\_  
Tbg. Inj. Pres. \_\_\_\_\_

Pressured annulus up to 560 psi. for 30 mins. Test passed ~~failed~~

REMARKS: Pressured up to 560psi - held at 560psi for full 30 min test.

TEST PASSED

1000# spring 1 hour clock - 1 hour chart -

By [Signature]  
(Operator Representative)

Witness [Signature] NMOCB  
(NMOCB)

Craig Lange Wellsite Leader  
(Position)

Revised 02-11-02