NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410 (505) 334-6178 FAX: (505) 334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Tes	st	8/8/2017	Operator Burlington Resources Hilcorp API # 300450640						PI # 3004506405
Property Na	ame Cl	LEVELAND		Well No.	6	Location: Unit I	3 Section	21 Tow	nship 027N Range 009W
Well Status Shut-in			Initial PSI: Tubing45			Intermediate	ntermediate Casing45 Bradenhead0		
OPE	N BRAD	DENHEAD A	ND INTE	ERMEDIATE	TO A	TMOSPHERE IN	DIVIDUALI	Y FOR	15 MINUTES EACH
T C		F	RESSUR	RE			FL	OW CHA	RACTERISTICS
Testing		BRADENHEA		INTE			BRADE	NHEAD	INTERMEDIATE
TIME	ВН	Int	Csg	Int	Csg	Steady Flo	W		
5 min	0		45						
10 min	0		45			Surges			
15 min	0		45			Down to N	othing		
20 min						Nothing	`	Y	
						Gas			
25 min						Gas & Wa	tor		The same of the sa
30 min							tei		The state of the s
				•		Water			
If Bradenh	ead flov	ved water, ch	eck all o	f the descrip	tions t	hat apply below:			
		FRES	-			SULFUR BLACK			
If Intermed	liate flov	wed water. cl	neck all o	f the descrir	otions t	hat apply below:			
CLEAR FRES		-			SULFUR				
5 MINUTE	SHUT-II	N PRESSURE	Bra	adenhead	0	Intermed	diate		BIV DIST 3
REMARKS								OIL	CONS. DIV DIST. 3
No pressure on BH. ACOI well									AUG 1 7 2017
Tested By	Ishim			W	itness				