<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III

1000 Rio Brazos Road, Aztec, NM 87410

District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

1

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-129 Revised August 1, 2011

Submit one copy to appropriate District Office

NFO Permit No. \_\_

(For Division Use Only)

## APPLICATION FOR EXCEPTION TO NO-FLARE RULE 19.15.18.12


(See Rule 19.15.18.12 NMAC and Rule 19.15.7.37 NMAC)

A.	Applicant WPX Energy Production, LLC ,		
	whose address is P.O. Box 640, Aztec NM 87410		
	hereby requests an exception to Rule 19.15.18.12 for <u>2</u> days or until <u>9/11 Yr_2017</u> , for the following described tank battery (or LACT):  Name of Lease <u>W Lybrook Unit 752H</u> Name of Pool <u>Lybrook Mancos W</u>		
	Location of Battery: Unit Letter F Sec	tion 13 Township 23N Range 9W	
	Number of wells producing into battery	6	
В.	Based upon oil production of $\underline{450}$ barrels per day, the estimated * volume of gas to be flared is		
	<u><b>600</b></u> MCF; Value <u><b>1746</b></u> per day.	oil cons. DIV DIST. 3	
C.	Name and location of nearest gas gathering facility:  Williams Field Service, H-28, Sec 33 T24N, R8W  SEP 15 2017		
D.	Distance Built Estimated cost of connection		
E.	This exception is requested for the following reasons: High Oxygen Level		
	WPX notified Charlie Perrin(NMOCD) & David Mankiewicz (BLM) & received verbal approval for an Emergency Flare for <b>W Lybrook Unit 752H</b> on 9/8/17, for 2 days due to a workover rig on <b>W Lybrook Unit 752H</b> and caused high oxygen level in the pipeline.		
	This well flared an accumulated volume of 5045mcf & has not been returned to production as of 9/11/17.		
OPERATOR I hereby certify that the rules and regulations of the Oil Conservation		OIL CONSERVATION DIVISION	
Division have been complied with and that the information given above is true and complete to the best of my knowledge and belief.		Approved Until 9-1/-/7	
Signature Man 27100		By Chall Horn	
Printed Name & Title Marie E. Florez Permit Tech		Title SUPERVISOR DISTRICT #3	
E-mail Address marie.jaramillo@wpxenergy.com		Date 9.15.17	
Date <u>9/13/1</u>			
Gas-Oil ratio test may be required to verify estimated gas volume			

ratio test may be required to verify estimated gas volume.

## W Lybrook Unit 752H shares w/ 710H Pad





## Oxygen Level decreased-9/11/17 but extended the Flare extension due to the workover on the 752H

