## RECEIVED

Form 3160-5 (June 2015)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SEP 1 9 2017

FORM APPROVED OMB No. 1004-0137 Expires: January 31, 2018

5. Lease Serial No.

	BOREAU OF EARD MAIN				N0G14031948		
SUNDRY NOTICES AND REPORTS ON WELL Son Field Office					6. If Indian, Allottee	e or Tribe Name	
	this form for proposals a vell. Use Form 3160-3 (A				nt		
SUBMIT IN TRIPLICATE - Other instructions on page 2  1. Type of Well					7. If Unit of CA/Agreement, Name and/or No. NMNM 135216A		
☐ Oil Well ☐ Gas Well ☐ Other				8. Well Name and No. W Lybrook Unit 716H			
2. Name of Operator WPX Energy Production, LLC				9. API Well No. 30-045-35813			
3a. Address       3b. Phone No.         PO Box 640       Aztec, NM 87410       505-333-181			(include area code)  10. Field and Pool or Exploratory Lybrook Mancos W				
4. Location of Well (Footage, Sec SHL: 1835' FSL & 624' FEL S BHL: 1537' FSL & 330' FWL		11. Country or Parish, State San Juan, NM					
12.	CHECK THE APPROPRIATE B	OX(ES) TO IND	CATE NATURE	OF NOTIC	CE, REPORT OR OT	THER DATA	
TYPE OF SUBMISSION TYPE OF ACTION							
□ Notice of Intent	Acidize	Deepen		☐ Production (Start/Resume)		☐Water ShutOff	
	☐Alter Casing	Hydraulic	lic Fracturing		mation	□Wel	l Integrity
Subsequent Report	☐ Casing Repair	☐ New Con	truction		⊠Oth	er Final Casing	
	☐ Change Plans	☐ Plug and	d Abandon Temporarily		porarily Abandon		
Final Abandonment Notice	☐Convert to Injection	☐Plug Back	ck 🔲 V		ter Disposal		
66							
completion or recompletion in a not reclamation, have been completed is ready for final inspection.)  //8/17- MIRU. PSI 7" Intermediate //9/17-Drilling ahead 6-1/8" latera //10/17- TD 6-1/8" lateral @ 1194/11/17-Ran 150 Its & 2 pup its of the ement 5,000 Psi Test on Lines Flucollowed by Primary Cement mixed for 2% KCL, & 20 fresh 34.6, 2% KCL ting out of Liner Hanger, W/ Pum/12/17-Ran Tie Back Frac String //	1' (TVD 4813'). 4.5" 11.6#, P-110, CSG set @ 1194 sh Water @ 8.3# {10 BBLS }, follow @ 13.3# YD-1.36 water 6.01 gal/s }@ 2.5 BPM Land Plug 1,440 PSI & p truck Circ Out 40 Bbl Good Ceme 124 jts & 5 pups of 4.5", 11.6# P-1 2,000psi for 30 min, good test reco	All tested good  O', LC @ 11893', wed by Tuned Sp: sx { 152 Bbls/630 Bump up to 2,40 ent to Surface. N 10, LT&C, O'GL t	and recorded on RSI @ 11870', TO acer @ 11.5# (40 sks) ExtendaCem 10 PSI & Hold 5 mid BOPE o 5,255' MD TOL	chart. Solution of the chart. Solution of the chart. Solution of the chart of the c	FARI By Displacement Teld got 1.5 Bbl Back on Mandrel 35k & 30k	CEPTED FOR RICE OF A CONTROL OF THE	ECORD  17  OFFICE  4 40 Bbls MMCR,60 Bbls own 9/11/2017 20:30.
						OIL CONS	DIV DIST. 3
14. I hereby certify that the foregoing is true and correct. Name ( <i>Printed/Typed</i> ) Lacey Granillo			Title: Permit Tech III			SEP 22 2017	
Signature	Date: 9/19/17						
	THE SPACE	FOR FEDE	RAL OR STA	TE OF	CE USE		
Approved by							
			Title			Date	
Conditions of approval, if any, are	attached. Approval of this notice of	loes not warrant of	or				

Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

certify that the applicant holds legal or equitable title to those rights in the subject lease

which would entitle the applicant to conduct operations thereon.



Office