



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

~~(TA OR UIC)~~

Date of Test 10-10-2017 Operator Hilcorp API # 30-039-20321

Property Name San Juan 27-4 Unit Well # 55 Location: Unit 6 Sec 5 Twn 27 Rge 4

Land Type:

State _____
Federal X
Private _____
Indian _____

OIL CONS. DIV DIST. 3

OCT 10 2017

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas X
Pressure observation _____

Temporarily Abandoned Well ~~(N)~~ TA Expires: _____

Casing Pres. Ø
Bradenhead Pres. Ø
Tubing Pres. Ø
Int. Casing Pres. Ø

Tbg. SI Pres. _____
Tbg. Inj. Pres. _____

Max. Inj. Pres. _____

Pressured annulus up to 555 psi. for 30 mins. Test passed ~~failed~~

REMARKS: Casing repair - 1hr chart - 1000# spring -

Pressured up to 555psi - Drop 15psi to 540psi first 10 min of test. Holding at
540psi at 20 min. Held at 540psi for remainder of test.

By Andrew S Fordyce
(Operator Representative)

Witness Jh NMOC
(NMOC)

Wellsite Supervisor
(Position)

Revised 02-11-02