

## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 67410
(505) 334-6170 FAX: (505) 334-6170
http://emnrd.state.nm.us/oci/District Bi/3distric.htm

## **BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of Test 31-17 Operator Geath Jestern Dr. 11 GAPI #30-045-23091	
Property Name 55 Decker Well No. 3 A Location: Unit Section 8 Township 32 Range 11	
Well Status(Shut-In or Producing) Initial PSI: Tubing 120 Intermediate Casing 268 Bradenhead 57	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME 15 268	Steady Flow
10 min 15 268	Surges
15 min 15 268	Down to Nothing
20 min 14 268	Nothing
25 min_	Gas
30 min_	Gas & Water
	Water
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY	SULFURBLACKOIL CONS. DIV DIST.
5 MINUTE SHUT-IN PRESSURE BRADENHEAD SI INTERMEDIATE OCT 1 2 2017	
REMARKS:	
hard blow through out test . TRETO COMPTEST	
Lead Slow House out test  ***FAILURE TO COMPLY  ***FAILURE TO COMPLY  WITH BRADENHEAD TEST  WITH BRADENHEAD TEST  WITH BRADENHEAD TEST  WITH BRADENHEAD TEST	
By Colar Witness WITH BRANDUM DATED  WITH BRANDUM DATED  MEMORANDUM DATED  FEBRUARY 14, 2017	
(Position)	
E-mail address	