



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-31-17 Operator Geetha Lakshmi D. N. G. API #30-0 45-27427
Property Name S.E. Dedcor Well No. 10 Location: Unit K Section 7 Township 32 Range 11
Well Status (Shut-In or Producing) Initial PSI: Tubing 92 Intermediate Casing 152 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
5 min	0		152		
10 min	0		152		
15 min	0		152		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	X
Nothing	
Gas	X
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

OIL CONS. DIV DIST. 3

OCT 12 2017

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE

REMARKS:

Compressor on pipeline

By Colleen Keller

Witness

(Position)

E-mail address

**** FAILURE TO COMPLY
WITH BRADENHEAD TEST
MEMORANDUM DATED
FEBRUARY 14, 2017