



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrdd.state.nm.us/ocd/District II/3distric.htm](http://emrdd.state.nm.us/ocd/District%20II/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 11-7-17 Operator Great Western API #30-0 45-07663
Property Name Callow Fed Well No. 1 Location: Unit Section 33 Township 29 Range 13
Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate N/A Casing 120 Bradenhead 120

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>0</u>		
10 min	<u>0</u>		<u>0</u>		
15 min	<u>0</u>		<u>0</u>		
20 min	<u>0</u>		<u>0</u>		
<u>22</u> min	<u>0</u>		<u>0</u>		
30 min					

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow ✓
Surges
Down to Nothing
Nothing
Gas ✓
Gas & Water
Water

OIL CONS. DIV. DIST. 3
NOV 07 2017

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 6

INTERMEDIATE N/A

REMARKS:

Hard to read low when opened. Light blow 5-10-15-20-22
Started running went to 5 min shut in
tubing has pressure plug - not producing

By Alan
Switcher
(Position)

Witness Donna Ruth King

E-mail address