Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

5. Lease Serial No.

NMNM-03404

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an		6. If Indian, Allottee or Tribe Name		
abandoned well. Use Form 3160-3 (APD)		- X0XX :: 0.01/1	V 27	
SUBMIT IN TRIPLICATE - Other instructions on page 2. 1. Type of Well		7. If Unit of CA/Agreement, Name and/or No. San Juan 31-6 Unit		
Oil Well X Gas Well Other		8. Well Name and No. San Juan 31-6 Unit 212A		
2. Name of Operator		9. API Well No.		
Hilcorp Energy Company			39-27812	
3a. Address PO Box 4700, Farmington, NM 87499	hone No. (include area code) 505-599-3400	10. Field and Pool or Exploratory Area Basin Fruitland Coal		
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)	000 000 0400	11. Country or Parish, State		
Surface Unit P (SESE), 1311' FSL & 610' FEL, S	sec . 5, T30N, R06W	Rio Arriba	New Mexico	
12. CHECK THE APPROPRIATE BOX(ES) TO I	NDICATE NATURE OF NOT	ICE, REPORT OR OTHE	ER DATA	
TYPE OF SUBMISSION	SUBMISSION TYPE OF ACTION			
Notice of Intent Acidize I	Deepen Pr	oduction (Start/Resume)	Water Shut-Off	
		eclamation	Well Integrity	
Subsequent Report Casing Repair	New Construction Re	ecomplete	X Other	
Change Plans F	Plug and Abandon Te	emporarily Abandon	FAN	
X Final Abandonment Notice Convert to Injection	Plug Back W	ater Disposal		
The subject well was P&A'd on 5/17/2013. Reclamatio approval. The location was inspected and passed on Hilcorp Energy Company bond.	-		-	
	OIL CONS. DIV D	IST. 3	RECEIVED	
	NOV 20 20	17	OCT 3 1 2017	
			Farmington Field Office Bureau of Land Management	
14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)				
Christine Brock	Title Operations/Re	Title Operations/Regulatory Technician		
Signature Unisting Lack	Date 10 31 1	Date 10 31 17		
THIS SPACE FOR FE	DERAL OR STATE OFFI	CE USE		
Approved by			, ,	
Sarch N Sicos	Title &	up MRS	Date 11/17/17	
Conditions of approval, if any, are attached. Approval of this notice does not warrant that the applicant holds legal or equitable title to those rights in the subject lease whice entitle the applicant to conduct operations thereon.		90		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any

false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instruction on page 2)

NMOCD~

RCC Reclamation Completion Location Name: 544 JUAN 31-6 21219 Date: 10-27-2017 UL-Sec-Twn-Rng: P" T3DN R6W Sec 5 Lat/Long: 36.85778 -107.47917 AP#: 30-039-27812 County/State: RIO ARRIVA NM Surface Owner: Lease# NM NM - 03404 Pipeline Owner: Twin/Co-Locate Well Name & Operator: Agency Inspector-Onsite: Seed Moc Incomplete Final Reclamation Interim Reclamation Remediation 3rd party pipeline removed Facilities stripped Have pit sample results been approved Anchors removed Certificate of waste issued & approved Has water been removed from pit Equipment and piping removed Have pit marker photos been taken Power poles removed Has certificate of waste been Issued & approved Width: Cathodic protection removed Have all pit contents been removed Length: Vegetative cages removed Date of Excavation Start: Has sample after content removal been taken ls location contoured CMP's removed Date of Excavation End: Non native gravel buried or removed is there 4' of cover over pit Date of Backfill Start: Noxious weeds removed or sprayed Date of Backfill End: Has top soil been spread evenly Has all non-native gravel been buried or removed Insvasive weeds removed or sprayed Yards Hauled Out: Impacted Soil Hauled To: Has oit liner been removed Contouring complete Yards Hauled In: Has all trash been removed Top soil spread Diversions clean and functional Fresh Soll Hauled in From: Have all weeds been removed Teardrop allows vehicle access to all facilities Silt trap clean and functional Approval to backful Drainage ditches allow adequate run off Cattle guard / gates removed Back fill mechanically compacted All non-traffic areas disked property Cellar / mouse hole covered Facilities reset Trash and debri removed All non-traffic areas seeded Erosion under control Seeded areas have been mulched Location properly ripped Close Out Completed Noxious weeds have been removed or sprayed Location properly disked Soil Removal Sundry Ready to be Flied Location seeded invasive weeds have been removed or sprayed Photo transect installed Barriers set to deter traffic Access road properly closed Silt traps are functional Culverts are functional Public use controlled Barriers in place Upper diversion is functional Grazing controlled Erosion under control / P&A marker installed & Jegible Photo transect installed Well sign removed Have wellhead cages and jersey barriers been removed Growth at least 70% lave reclamation pictures been taken Trash and debris removed from location Growth at least 70% Final reclamation photos taken Agency Inspection Date: Agency Inspection Date: Sundry is ready to file FAN Ready to be filed Comments: Comments: Comments: SUBMIT FAN