



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

OIL CON. DIV. DIST. 3

000124-2017

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10-24-2017 Operator Great Western API #30-0 45-23031 JK

Property Name JE Decker Well No. 3A Location: Unit L Section 8 Township 32 Range 11

Well Status (~~Shut In~~ or Producing) Initial PSI: Tubing 115 Intermediate NA Casing 270 Bradenhead 49

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	18	NA	270		
10 min	18		270		
15 min	18		270		
20 min	17		270		
25 min	17		270		
30 min	17		270		

FLOW CHARACTERISTICS		BRADENHEAD	INTERMEDIATE
Steady Flow	X		
Surges			
Down to Nothing			
Nothing			
Gas	X		
Gas & Water			
Water			

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 48

INTERMEDIATE NA

REMARKS: 1" valve -

Hard steady flow when BH was opened - Hard steady flow at 3 min.
Hard steady flow at 5 min. Hard steady flow at 10 min. Hard steady flow at 15 min.
Hard steady flow at 20 min same at 25 min Hard steady flow for 30 min -

By C. Harker

Witness JK Harker NMCO

(Position)

E-mail address _____