## District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III

1000 Rio Brazos Road, Aztec, NM 87410

1220 S. St. Francis Dr., Santa Fe, NM 87505

District IV

## State of New Mexico

Energy Minerals and Natural Resources

For drilling and production facilities, submit to

Form C-144

June 1, 2004

## Oil Conservation Division

1220 South St. Francis Dr. Santa Fe, NM 87505

For drilling and production facilities, submit to appropriate NMOCD District Office.

For downstream facilities, submit to Santa Fe Office

Is pit or below-grade tar	de Tank Registration or Clonk covered by a "general plan"? Yes or below-grade tank Closure of a pit or	X No	
Deperator: BURLINGTON RESOURCES OIL & GAS COMPANY LP Telephone:  Address: 3401 E. 30TH STREET, FARMINGTON, NM 87402	505-326-9700 e-mail address: Pthompson	Formation: Blanco	Pictured Cliffs
			vate Indian
Pit Type: Drilling Production Disposal Workover Example Emergency Unlined Ix Disposal Disposal Disposal Disposal Disposal Price Disposal D	Below-grade tank  Volume: bbl Type of fluid:  Construction material:  Double-walled, with leak detection? Yes If	If not, explain why not.	_
Depth to ground water (vertical distance from bottom of pit to seasonal high vater elevation of ground water.)	Less than 50 feet 50 feet or more, but less than 100 feet 100 feet or more	(20 points) (10 points) ( 0 points) <b>0</b>	
Wellhead protection area: (Less than 200 feet from a private domestic water source, or less than 1000 feet from all other water sources.)	Yes No	(20 points) ( 0 points) <b>0</b>	
Distance to surface water: (horizontal distance to all wetlands, playas, irrigation canals, ditches, and perennial and ephemeral watercourses.)	Less than 200 feet 200 feet or more, but less than 1000 feet 1000 feet or more	(20 points) (10 points) <b>0</b> ( 0 points)	
	Ranking Score (Total Points)	0	
If this is a pit closure: (1) attach a diagram of the facility showing the pit's relativour are burying in place) onsite	. (3) Attach a g	eneral description of remedial action	on taken including
Additional Comments:		45	43
See attached well pad diagram for direction and distance of	f pit from well head	MAR 2008	<u> </u>
		COL D	v. 🗒
		C DIST. S	
		( D) 25	J.
I hereby certify that the information above is true and complete to the best of m	y knowledge and belief. I further certify that th	e above-described pit or below-g	rade tank has

Printed Name/Title Philana Thompson / Regulatory Associate

Signature Signat

Approval:

3-7-06

TERLITY ON & GAS INSPECTOR, DIST. #8

Signatur

Denyfort

Date: MAR 1 0 2006

