



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emmr.state.nm.us/ocd/District/III3district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 12-20-2017 Operator Hilcorp Energy Co. API #30-045-60060

Property Name Moore LS Well No. 3 Location: Unit Section 13 Township 32 Range 12

Well Status(Shut-In or Producing) Initial PSI: Tubing 98 Intermediate 0 Casing 107 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	107	0	108
10 min	0	0	107	0	108
15 min	0	0	107	0	108
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	X
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD Opsi

INTERMEDIATE Opsi

REMARKS:

Nothing on BH when opened. Nothing on BH after 5min shut in.
Nothing on intermediate when opened. Nothing on intermediate after 5min
shut in.

By Brian T. Harvey
(Position)

Witness James K. H. NMOC

E-mail address

OIL CONS. DIV DIST. 3
DEC 20 2017