

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

OIL CONS. DIV DIST. 3

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

JAN 05 2018

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Hilcorp Energy Company	Contact Jennifer Deal
Address 9a CR 5793	Telephone No. (505) 324-5128
Facility Name Turner B Com 1A	Facility Type Gas Well

Surface Owner Private	Mineral Owner	API No. 30-045-22376
-----------------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter F	Section 02	Township 30N	Range 09W	Feet from the 1830	North/South Line North	Feet from the 1548	East/West Line West	County San Juan County
---------------	------------	--------------	-----------	--------------------	------------------------	--------------------	---------------------	------------------------

Latitude 36.8424568 Longitude -107.7539749 NAD83

NATURE OF RELEASE

Type of Release Hydrocarbon/Oil	Volume of Release 40 BBLs	Volume Recovered 40bbls
Source of Release Tank	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 12/20/2017 @2:00pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Vanessa Fields & Brandon Foley	
By Whom? Paul Keloff	Date and Hour 12/21/2017 @9:00am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

Operator noticed Over the Top spill on 400bbl oil tank. Oil stayed within secondary containment

Describe Area Affected and Cleanup Action Taken.\*

Hilcorp Energy Company (HEC) hydrovaced a 60'x15'x.25' area to clean up impacted soil. Confirmation sampling is scheduled for 1/4/2018

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Jennifer Deal	Approved by Environmental Specialist: 	
Title: Environmental Specialist	Approval Date: 1/8/2018	Expiration Date:
E-mail Address: jdeal@hilcorp.com	Conditions of Approval: Sample Area 8015/8021 Fully delineate Site	Attached <input type="checkbox"/>
Date: 1/2/2018	Phone: (505) 324-5128	

\* Attach Additional Sheets If Necessary

Provide 24 Notification  
Prior to Sampling  
NVF 1800240565