



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3distric.htm>

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

JAN 09 2018

Date of Test 1-9-2018 Operator Hilcorp Energy API #30-0 39-27739

Property Name San Juan 306 Unit Well No. 4915 Location: Unit F Section 25 Township 30 Range 6

Well Status(Shut-In or Producing) Initial PSI: Tubing 0 Intermediate NA Casing 6 Bradenhead -1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0	NA	6		
10 min	0		6		
15 min	0		6		
20 min	0		6		
25 min	0		6		
30 min	0		6		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	X	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 psi

INTERMEDIATE NA

REMARKS:

Nothing on BH when opened. Nothing on BH after 5 minute shut in.

By Brian / Cam
Field operator
(Position)

Witness J. H. NMCD

E-mail address _____