



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

## MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 1-4-2018 Operator CCI San Juan API # 30-045-35172

Property Name Pathfinder AGI Well # 1 Location: Unit F Sec 1 Twn 29 Rge 5

OIL CONS. DIV DIST. 3

Land Type:

State \_\_\_\_\_  
Federal \_\_\_\_\_  
Private X  
Indian \_\_\_\_\_

JAN 04 2018

Well Type:

Water Injection \_\_\_\_\_  
Salt Water Disposal \_\_\_\_\_  
Gas Injection X  
Producing Oil/Gas \_\_\_\_\_  
Pressure observation \_\_\_\_\_

Temporarily Abandoned Well (N): \_\_\_\_\_ TA Expires: \_\_\_\_\_

Casing Pres. 0  
Bradenhead Pres. 0  
Tubing Pres. 1400  
Int. Casing Pres. 0

Tbg. SI Pres. \_\_\_\_\_  
Tbg. Inj. Pres. \_\_\_\_\_

Max. Inj. Pres. 2160 psi

Pressured annulus up to 590-558 psi. for 30 mins. Test passed/failed

### REMARKS:

Using Diesel for test. Pressured up to (593psi gauge) 590psi chert - Drop of approx 20psi in first 5min to 570psi - Cont drop to approx 565psi at 10min - 560psi at 15min. 558psi at 25min. Held at 558psi for last 10min of test.

Packer set at: 6285' - perf 6352'-6490'

Thermostat 1000# spring  
Inst Cal. 10-4-17

By [Signature]  
(Operator Representative)

Witness [Signature]  
(NMOCD)

ESSH Specialist  
(Position)

Revised 02-11-02