



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3

JAN 17 2018

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 1/17/2018 Operator BP America API # 30-045-20006
Property Name Gallego 3 Canyon Unit Well No. 255 Location: Unit P Section 14 Township 28 Range 12
Well Status (Shut-In or Producing) Initial PSI: Tubing 158 Intermediate NA Casing 39 Bradenhead -0.3

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		37.5		
10 min	0		37.5		
15 min	0		37.5		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	X
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE NA

REMARKS:

BH w/ MIT, light suction on BH, down to nothing in 3 sec.

By Adam Suarez
Well Intervention Team Lead
(Position)

Witness John P. Kelly

E-mail address _____