



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONS. DIV DIST. 3

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

JAN 02 2018

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 08/15/17 Operator BP America Production Company API # 3004522120

Property Name FLORANCE 018A-MV Location: Unit E Section 11 Township 30 Range 9
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 49.4 Intermediate Casing 65.7 Bradenhead 42.4

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	0.1	66.9				Steady Flow	
10 minutes	0.1	65.2				Surges	
15 minutes	0.1	63.8				Down to Nothing	1 second
20 minutes	0.1	63.1				No Flow	
25 minutes	0	62.9				Gas	
30 minutes	0	64.7				Gas and Water	
5 minute SI	2.7					Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

REMARKS:

Compressor on location running casing closed pulled gas samples on bradenhead, casing and tubing string.

By Matthew Yazzie Witness