



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 4-19-06 Operator Mountain States API # 30-03120115

Property Name Hospih Sand Mt. Well # 58 Location: Unit 0 Sec 36 Twn 18 Rge 9

Land Type:

State _____
Federal _____
Private ☒ _____
Indian _____

Well Type:

Water Injection ☒ _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

Temporarily Abandoned Well (Y/N) (N)

TA Expires: _____

Casing Pres. 0

Tbg. SI Pres. _____

Max. Inj. Pres. _____

Bradenhead Pres. _____

Tbg. Inj. Pres. _____


Tubing Pres. 0

Int. Casing Pres. N/A

Pressured annulus up to 560 psi. for 538 mins. Test passed failed

REMARKS:

No bradenhead.




By [Signature]
(Operator Representative)

Witness Monica Cuchling
(NMOCD)

Prod. Supt.
(Position)

Revised 02-11-02



GRAPHIC CONTROLS CORPORATION
BUFFALO, NEW YORK
CHART NO. 30-031-2015
MC MP-1000-150F
36-18-9
CHART PUT ON 04-12-06
LOCATION Hospital Sand Unit #58
REMARKS
TAKEN OFF

MIDNIGHT

6 AM

NOON

6 PM

PRINTED IN U.S.A.