Form 3160-5 (August 2007)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

		5. Lease Serial No.				
	NMSF-079001-A					
SUNDRY NOTICES AND REF		6. If Indian, Allottee or Tribe	Name			
Do not use this form for proposals						
abandoned well. Use Form 3160-3	APD) for such proposals.	<u> </u>				
SUBMIT IN TRIPLICATE - Other in	nstructions on page 2.	7. If Unit of CA/Agreement, 1	Name and/or No.			
. Type of Well		1				
Oil Well X Gas Well Other		8. Well Name and No.				
		ŀ	lowell B 3			
2. Name of Operator		9. API Well No.				
Hilcorp Energy Comp	30-039-07906					
Ba. Address	3b. Phone No. (include area code)	0. Field and Pool or Exploratory Area				
PO Box 4700, Farmington, NM 87499	505-599-3400	Basin Fruitland Coal				
Location of Well (Footage, Sec., T.,R.,M., or Survey Description)	11. Country or Parish, State					
Surface Unit M (SWSW), 990' FSL & 890'	Rio Arriba	, New Mexico				
12. CHECK THE APPROPRIATE BOX(ES	S) TO INDICATE NATURE OF NO	TICE, REPORT OR OTH	IER DATA			
TYPE OF SUBMISSION	PE OF SUBMISSION TYPE OF AC					
Notice of Intent Acidize	Deepen P	Production (Start/Resume)	Water Shut-Off			
Alter Casing	Fracture Treat R	Reclamation	Well Integrity			
Subsequent Report Casing Repair		Recomplete	X Other			
Change Plans			FAN			
		emporarily Abandon	FAN			
X Final Abandonment Notice Convert to Injection		Vater Disposal				
3. Describe Proposed or Completed Operation: Clearly state all pertinent de If the proposal is to deepen directionally or recomplete horizontally, giv Attach the bond under which the work will be performed or provide the following completion of the involved operations. If the operation result Testing has been completed. Final Abandonment Notices must be filed determined that the site is ready for final inspection.)	ve subsurface locations and measured and tr e Bond No. on file with BLM/BIA. Require ts in a multiple completion or recompletion	ue vertical depths of all pertine d subsequent reports must be f in a new interval, a Form 3160	ent markers and zones. Tiled within 30 days 1-4 must be filed once			
The subject well was P&A'd on 09/27/00. Reclan approval. The location was inspected and pass remove this well from the Hilcorp Energy Comp	on 1/19/2018 with Bob Switze		-			
	au agus mu nic	er q	RECEIVED			
	OIL CONS. DIV DIS	JII V	1001 00			
	EB 12	) N 1 Q	JAN 29 2013			
	1 to 1 to 1	10 10	140.0			
			Farmington Field Office			
		Bi	ureau of Land Managemer			

nt

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)			
Etta Trujillo	Title	Operations/Regulatory Technic	ian Sr
Signature The The	Date	1-29-18	
THIS SPACE FOR FEI	DERAL O	R STATE OFFICE USE	
Approved by Yeather of pung		Actinicy Title Sypu NR	S Date 2/2/2018
Conditions of approval, if any, are attached. Approval of this notice does not warrant of that the applicant holds legal or equitable title to those rights in the subject lease which entitle the applicant to conduct operations thereon.	-	Office PPO	
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any false, fictitious or fraudulent statements or representations as to any matter within its ju		wingly and willfully to make to any departmen	nt or agency of the United States any

(Instruction on page 2)



RCC Reclamation Completion			Location Name: How SIL B 3			Date: /-/9-2018 Revision 2 (3/7/17)	
PHI: 30-039-07906				UL-Sec-Twn-Rng: T30N R7W "M" Sec	<u>.3</u>		Lat/Long: 36.83699 -107.563977  County/State: RIO ARRIBA NM
urface Owner: BLM				Leasett			County/State: RIO ARRIBA NIM
				Twin/Co-Locate Well Name & Operator:			·
ipeline Owner:	Ape	ncv.	Inspe	ctor: // / Contractor:			Seed Mix:
onsite: Eric Smith	-6-			1200 Sough			
Interim Reclamation	Completed	Incomplete	NA	Final Reclamation	Incomplete	NA	Remediation Completed NAM
lave pit sample results been approved		_	$\dashv$	3rd party pipeline removed		力	Facilities stripped
lave pit sample results been approved las water been removed from pit				Anchors removed	L	$\Box$	Certificate of waste issued & approved
as water been removed from pit			$\neg$	Equipment and piping removed	Ľ		Depth;
lave pit marker photos been taken las certificate of waste been issued & approved	П	_		Power poles removed		$\Box$	Width:
las certilicate of waste been removed				Cathodic protection removed		4	Length:
las sample after content removal been taken				Vegetative cages removed	┙_		Date of Excavation Start:
a location contoured			П	CMP's removed V	1	4-4	Date of Excavation End:
there 4' of cover over pit				Non native gravel buried or removed	┷	14	Date of Backfill Start:
las top soil been apread evenly				Noxious waeds removed or sprayed	4	14	Dale of Backfill End:
las all non-native gravel been buried or removed				Insvasive weeds removed or sprayed	,	V	Yards Hauled Out:
as pil liner been removed				Contouring complete V	Ά-		Impacted Soil Hauted To:
as all trash been removed				Top soil spread	4	-1	Yards Hauled In:
ave all weeds been removed		<u> </u>	Ш	Diversions clean and functional		-	Fresh Soil Hauled in From:
ardrop allows vehicle access to all facililes				Sili trap clean and functional · ✓		<u></u>	Approval to backill
rainage ditches allow adequate run off		L_		Cattle guard / gates removed	<del>/</del>	_	Back (III mechanically compacted
non-traffic areas disked properly				Cellar / mouse hole covered /	,	4	Facilities reset
non-traffic areas seeded				Erosion under control V	4		Trash and debri removed
eded areas have been mulched	<u>L</u>	<u> 1 _</u>		Location properly ripped	4	┷	Close Out Completed
xious weeds have been removed or sprayed	Г	Γ.		Location property disked . v	Ĺ!		Soil Removal Sundry Ready to be Filed
rasive weeds have been removed or sprayed	1			Location seeded V	<u>.</u>		·
miera set to deter traffic	T	1		Photo transect installed		7	
t traps are functional		1		Access road properly closed	Z		
Iverts are functional	T	+-		Public use controlled !	ZI.	$\top$	
per diversion is functional	1	十一	1	Barriers in place	7	$\top$	
	╅	+-	1	Grazing controlled	71	$\neg$	1
we wellhead cages and jersey barriers been removed	1	+-	$\top$	P&A marker installed & legible	7	$\neg$	1 <del></del>
ve reclamation pictures been taken	+-	+-	+-		ŻΤ		
owth at least 70%	+-	+-	┿		才	_	┧├ <del>┈╴┈┈┈┈┈┈┈┈┈</del> ┼┼
ency inspection Date:	╁╴	╫	┿╌		7	-+-	┪ <del>╏┈┈┈┈┈┈┈</del> ╌┼┼
ndry is ready to file	╁	+-	╁		7		┪ <del>┝╼╼╼╼╼</del> ╼╼╼╼╼╼╼ <del></del>
	╄	+-	┿	Agency Inspection Date:	-+		┧├ <del>────────</del>
	4	-	+-		<del>-</del> /-	-+-	┥ <del>┝╸╸</del>
·	ㅗ	┸	ᆚ	FAN Ready to be filed			Comments:
mments:				Comments: Submit fan			

'n

.