Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

				NMSF-078673				
	NDRY NOTICES AND REPORT				fame			
	se this form for proposals to di d well. Use Form 3160-3 (APD)			nd Management				
	SUBMIT IN TRIPLICATE - Other instruction	004/07	7. If Unit of CA/Agreement, Name and/or No.					
1. Type of Well		on page 2.		-				
Oil Well	X Gas Well Other			8. Well Name and No.				
			Schlosser WN Federal 4					
2. Name of Operator	Hilcorp Energy Company			9. API Well No. 30-045-07055				
3a. Address		Phone No. (include ar	ea code)	10. Field and Pool or Explorato				
PO Box 4700, Farming	ton, NM 87499	505-599-34	400	Bas	asin Dakota			
4. Location of Well (Footage, Sec., T.,		04 7001	DAOW	11. Country or Parish, State	N. Maria			
Surface Unit A (N	ENE), 1070' FNL & 1130' FEL,	Sec . 34, 128N,	R11VV	San Juan ,	New Mexico			
12 CHECK	THE APPROPRIATE BOX(ES) TO	INDICATE NATU	RE OF NO	TICE REPORT OR OTHE	R DATA			
TYPE OF SUBMISSION	THE ATTROTRIBLE BOX(EG) TO		PE OF AC					
	A siding				Water Shut Off			
Notice of Intent		Deepen Fracture Treat		roduction (Start/Resume)	Water Shut-Off Well Integrity			
Subsequent Report		New Construction		Lecomplete	X Other			
Subsequent Report		Plug and Abandon		emporarily Abandon	FAN			
X Final Abandonment Notice		Plug Back		Vater Disposal	27411			
	peration: Clearly state all pertinent details, in			A	ate duration thereof			
	P&A'd on 8/15/2005. Reclamation was inspected and passed on any bond.							
				CONS. DIV DIST. 8				
14. I hereby certify that the foregoing is	s true and correct. Name (Printed/Typed)				ž.			
Christine Brock		Title Op	erations/R	egulatory Technician				
Signature UMIST	the Brock	Date		2/6/2018				
	THIS SPACE FOR FE	DERAL OR ST	TATE OFF	ICE USE				
Approved by Saval N &	UA		Title &	epu NRS	Date 2/9/18			
**	thed. Approval of this notice does not warran the title to those rights in the subject lease whi		Office /	56				

entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any

RCC Reclamation Comple	etio	n		Location Name: ScHLOSSER WN (FED	EKA	4	#4	Date: 2-6-2018 Revision			
API#: 30-045-07055 Surface Owner: BL M		UL-Sec-Twn-Rng: A" Taby RIW Sec 34				Lat/Long: 36.622989 -107.	8	54	<u>, 7</u>		
		Lease# NMSF- 078673		Lat/Long: 36.622909 -107.98547 County/State: 5AN JUNN NEW MEXICO							
Pipeline Owner:				Twin/Co-Locate Well Name & Operator:							
Onsite:	Insp	Contractor:	Seed Mix:								
Interim Reclamation	Completed	Incomplete		Final Reclamation	Completed	Incomplete	NA	Remediation	Completed	Incomplete	NA NA
lave pit sample results been approved	1	\vdash	\vdash	3rd party pipeline removed	7			Facilities stripped	Н	Н	Г
las water been removed from pit	\neg	Т	П	Anchors removed		1		Certificate of waste issued & approved	_	П	ī
lave pit marker photos been taken		T	П	Equipment and piping removed		i		Depth:		М	Γ
las certificate of waste been issued & approved	_	1	П	Power poles ramoved	٦.,	一	П	Width:		П	Г
lavo all piì contente been removed	7	1	П	Cathodic protection removed	77	7	П	Length:		М	Г
las sample after content removal been taken	7-	1	П	Vegetative cages removed	75	7	\sqcap	Date of Excavation Start;		М	Г
s location contoured	\top	т	Н	CMP's removed	┪,	П	マ	Date of Excavation End:	Т	П	Г
s there 4' of cover over pil	+	+	Н	Non native gravel buried or removed	٠,	1	\dashv	Date of Back@ Start:	Η-	\vdash	r
fas top soil been spread eventy	+	t	Н	Noxious weeds removed or sprayed	1.7	H	\dashv	Date of Backill End:	_	Н	Г
las all non-native gravel been buried or removed	+	₩	Н	Insvesive weeds removed or sprayed	 Y.	-	\dashv	Yards Hauted Out:	_		_
as pil liner been removed	+	┼	Н	Contouring complete	+*	H	-1	Impacted Soil Hauled To:	-	\vdash	_
ias all trash been removed		┢	⊢┤	Top soil spread	+4		1	Yarda Hauled In:	-	Н	_
lave ell weeds been removed	4	⊢	Н	Oliversions clean and functional	+-	- 		Fresh Soil Hauded In From:	\vdash	⊢⊣	-
		!—	ы		12	Н	ᆛ			ш	,_
Teardrop allows vehicle access to all facililes	4_	┞-	ы	Sill trap clean and functional	+	Н	<u>Ľ</u>	Approval to backfill	_		_
Orainage dilches allow adequate run off	4	╙	щ	Cattle guard / gates removed	· ·	إبنا	4	Back fill mechanically compacted	-		
All non-traffic areas disked properly	丄	ட	Ш	Cellar / mouse hole covered		ш	_	Facilities reset			
All non-traffic areas seeded				Erosion under control .				Trash and debri removed			
Seeded areas have been mulched	T			Location properly ripped	1		. 1	Close Out Completed			Т
Voxdous weeds have been removed or sprayed	\top	П		Location properly disked	1/	П	\neg	Soil Removal Sundry Ready to be Filed		\neg	_
nvasive weeds have been removed or sprayed	1	_	П	Location seeded	7	\Box	7			\dashv	_
Renders set to deter traffic	+	Н	-	Photo transect installed	1.4	\vdash	-			\vdash	-
Stit traps are functional	+-	-	Н	Access road properly closed	+	⊢	\dashv			\dashv	_
Curverts are functional	+	Н	н	Public use controlled	+4	\vdash				\dashv	_
	4	ш	ш		4	Н	-	<u> </u>		_	_
Jpper diversion is functional	┸	Ш	ш	Barriers in place	10	Щ					
lave wellhead cages and jersey barriers been removed		1. 1		Grazing controlled							Ξ
lave reclamation pictures been taken	T			P&A marker installed & legible			П				_
Browth at least 70%	\top		\neg	Well sign removed	V		\neg			\neg	-
gency Inspection Date;	1	\Box	\neg	Growth at least 70%	17	_	Ч.			-+	-
undry is ready to file	+	-	\dashv	Trash and debris removed from location	1,	\vdash	-1		-	\dashv	_
	+			Final reclamation photos taken	-	\rightarrow					_
	+	-			44	\dashv	-			_	_
	+	ш	_		14	4	-			_	_
				FAN Ready to be filed							
ommonts:				Comments: SUBMIT FAN				Commonts:			

 ϵ_{\parallel}