Form 3160-5 (August 2007)

(Instruction on page 2)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

5. Lease Serial No.

6. If Indian, Allottee or Tribe Name

SF-078020

## SUNDRY NOTICES AND REPORTS ON WELLS

	well. Use Form 3160-3 (APD)	TOT SUCTI Propos	sausot Land	Management	
30	ons on page 2.		7. If Unit of CA/Agreement, Name and/or No.		
1. Type of Well	X Gas Well Other				uerfano Unit
Oil Well		8. Well Name and No.		fano Unit 190	
2. Name of Operator			9. API Well No.		
Hilcorp Energy Company			30-045-20419		
3a. Address		Phone No. (include area c		). Field and Pool or Explorat	-
PO Box 4700, Farmingt		505-599-3400			sin Dakota
4. Location of Well (Footage, Sec., T.,I Surface Unit B (N	WNE), 1025' FNL & 1840' FEL,	Sec . 1, T25N, R1		San Juan	, New Mexico
12. CHECK	THE APPROPRIATE BOX(ES) TO I	NDICATE NATURE	OF NOTIC	CE, REPORT OR OTH	ER DATA
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent	Acidize	Deepen	Prod	uction (Start/Resume)	Water Shut-Off
	Alter Casing	Fracture Treat	Recl	amation	Well Integrity
Subsequent Report  X Final Abandonment Notice	Casing Repair	New Construction	Reco	omplete	X Other
		Plug and Abandon		porarily Abandon	FAN
		Plug Back		er Disposal	
				o DIV DIST. 3	
			OIL CO	NS. DIV DIST. 3	
4. I hereby certify that the foregoing is	true and correct. Name (Printed/Typed)		OIL CO	B 1.5 2018	
I hereby certify that the foregoing is     Christine Brock	true and correct. Name (Printed/Typed)			B 1.5 2018	
	true and correct. Name (Printed/Typed)  The Back				
Christine Brock	true and correct. Name (Printed/Typed)  THIS SPACE FOR FE	- Title <b>Opera</b>	ations/Regi	ılatory Technician 2/6/2018	
Christine Brock	tine Brock	- Title <b>Opera</b>	ations/Regi	ılatory Technician 2/6/2018	
Signature Christine Brock  Signature Christine  Sig	THIS SPACE FOR FE	Title Opera  Date  DERAL OR STAT	ations/Regi	ılatory Technician 2/6/2018	Date 2/9/18
Christine Brock  Signature Christine Brock  sproved by  Christine Brock  Signature Christine Brock  And Christine Brock  Signature Christine Brock  Signatur	THIS SPACE FOR FE	Date  Dera Date  Dera Dera Dera Dera Dera Dera Dera Dera	TE OFFIC	2/6/2018 E USE	Date 2/9/18

NMOCD V

**RCC Reclamation Completion** Location Name: Huerfano 11-9-2017 190 Date: Revision 3 (3/21/17) UL-Sec-Twn-Rng: B 725N RIDW Sec 1 Lat/Long: 36, 43 46 -107.84433 APH: 30-045-20419 County/State: SAN JUAN SF 078020 NU Surface Owner: Lease# RLM Pipeline Owner: Twin/Co-Locate Well Name & Operator: The Sou the Seed Mix: Onsite: Contractor: Interim Reclamation **Final Reclamation** Remediation Facililes stripped Certificate of waste Issued & approved Have pil sample results been approved 3rd party pipeline removed Has water been removed from pit Depth: Width: Have pli marker photos been taken Equipment and piping removed Has certificate of waste been issued & approved Power poles removed lave all pit contents been removed Calhodic protection removed Length: Has sample after content removal been taken is location contoured Date of Excavation Start: Vegetative cages removed Date of Excavation End: CMP's removed is there 4' of cover over pit Non native gravel buried or removed Date of Backfill Start: r Date of Backfill End: Has top soil been spread evenly Has all non-native gravel been buried or removed Nodous weeds removed or sorgyed Yards Hauled Out: inavasive weeds removed or sprayed Impacted Soil Hauled To: las pit iner been removed Contouring complete Yards Hauted In: les ell trash been removed Too soil spread lave all weeds been removed Diversions clean and functional Fresh Soil Hauted in From: 1 Approval to backful Back fill mechanically compacted Teardrop allows vehicle access to all facilities Silt trap clean and functional 1 rainage ditches allow adequate run off Callie guard / gates removed All non-traffic areas disked properly Cellar / mouse hole covered 10 All non-traffic areas seeded Trash and debri removed Erosion under control <u>\_\_</u> Seeded areas have been mulched Location properly ripped Close Out Completed Noxious weeds have been removed or sprayed Soil Removal Sundry Ready to be Filed Location properly disked Invasive weeds have been removed or sprayed Location seeded Barriers set to deter traffic Photo transect installed Silt traps are functional Access road properly closed Culverts are functional Upper diversion is functional Borriers in place 7 Emsten under central Grazing controlled ~ Photo transact installed P&A marker installed & legible Well sign removed Have wellhead cages and jersey barriers been removed Growth at least 70% 456 Have reclamation pictures been taken Growth at least 70% Trash and debris removed from location Agency Inspection Date Final reclamation photos taken Agency Inspection Date: 11- 9- 2017 Sundry is ready to file FAN Ready to be filed Comments: WILL SIGN WHEN KISER IS REmoved ic's OHLY