NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3district.htm

OIL CONS. DIV DIST. 3
FEB 22 2018

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 2-22-2018 Operator Hilcorp Energy Co. API #30-0 45-26112

Property Name McCord Well No. 11E Location: Unit C Section 9 Township 30 Range 13

Well Status(Shut-In or Producing) Initial PSI: Tubing 143 Intermediate NA Casing 143 Bradenhead 136

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME 5 min	0	NA	146		
10 min	0		149		
15 min	0		151		
20 min	0		154		
25 min	0		157		
30 min	0		160		

FLOW CHARACTERISTICS

	BRADENHEAD	INTERMEDIATE
Steady Flow		NA
Surges		
Down to Nothing	X	
Nothing		
Gas	X	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR_____ FRESH_____ SALTY_____ SULFUR_____ BLACK_____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 3psi INTERMEDIATE_____

REMARKS:
Hard blow to vapors in 20 seconds - down to nothing in 3 minutes - Checked BH at 5min with gauge - 0psi - 3psi on BH after 5min shut- hard ~~blow~~ to nothing when opened. Hilcop to get gas sample ~~taken~~ in next few days.

By [signature] Witness [signature]

_____
(Position)

E-mail address _____