



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

NMOC

MAR 05 2018

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 3-5-18 Operator Enduring Res API #30-0 45-13040

Property Name Leilix latero Well No. 5 Location: Unit 11 Section 11 Township 27 Range 9

Well Status (Shut-In or Producing) Initial PSI: Tubing 51 Intermediate Casing 91 Bradenhead 4

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>1</u>		<u>91</u>		
10 min	<u>0</u>		<u>92</u>		
15 min	<u>2</u>		<u>92</u>		
20 min	<u>2</u>		<u>92</u>		
25 min	<u>2</u>		<u>92</u>		
30 min	<u>2</u>		<u>92</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>✓</u>	
Surges <u> </u>	
Down to Nothing <u> </u>	
Nothing <u> </u>	
Gas <u> </u>	
Gas & Water <u>✓</u>	
Water <u> </u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 2.9 INTERMEDIATE ✓

REMARKS:

10 seconds started flowing water per 100 ft steam
2 gallons in 5 min - 10 - valve to line to barrel 12 gallons.

By [Signature]

Witness Monica Cwikling

(Position)

E-mail address