



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrnr.state.nm.us/ocd/District III/3ddistrict.htm](http://emrnr.state.nm.us/ocd/District%20III/3ddistrict.htm)

NMOC

MAR 14 2018

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 3-14-2018 Operator Hilcorp API #30-045-30336

Property Name Maddox WNVed. Well No. 7 Location: Unit H Section 13 Township 30 Range 13

Well Status(Shut-In or Producing) Initial PSI: Tubing NA Intermediate NA Casing Ø Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead	INTERM			
	BH	Int	Csg	Int	Csg
TIME					
5 min	Ø	NA	Ø		
10 min	Ø		Ø		
15 min	Ø		Ø		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	X
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD Ø

INTERMEDIATE NA

REMARKS:

Well is TA'd. Nothing on BH when opened. Nothing on BH after five minute shut-in.

By Clingo

Witness Thom K. D. NMOC

Clingo Lingo Wellsite Supv
(Position)

E-mail address Clingo@hilcorp.com