



# NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

OIL CONS. DIV DIST. 3

JAN 02 2018

## BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6.26.17 Operator BP America Production Company API # 3004522513

Property Name LAWSON LS 001A-MV Location: Unit J Section 11 Township 31 Range 11  
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 121.7 Intermediate N/A Casing 64.1 Bradenhead 54.0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed		Intermediate Flowed	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor				
5 minutes	$\emptyset$	64.6	N/A	N/A	N/A	Steady Flow		N/A	
10 minutes	$\emptyset$	64.7				Surges			
15 minutes	$\emptyset$	64.4				Down to Nothing	3 sec		
20 minutes						No Flow	nothing after		
25 minutes						Gas			
30 minutes						Gas and Water			
5 minute SI						Water			

If bradenhead flowed water, check all of the descriptions that apply below:

Clear \_\_\_\_\_ Fresh \_\_\_\_\_ Salty \_\_\_\_\_ Sulfur \_\_\_\_\_ Black \_\_\_\_\_

5 Minute Shut-in Bradenhead 6.9 Intermediate N/A

### REMARKS:

Pulled gas sample from bradenhead, casing, & tubing.

By Eugenia Hamilton  
Lead Tech.

(Position)

Witness \_\_\_\_\_