



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III3distric.htm](http://emnr.state.nm.us/ocd/District%20III3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 3-26-18 Operator DJR Consulting API #30-0 45-29520
Property Name Callow Well No. 7 Location: Unit Section 33 Township 29 Range 13
Well Status (Shut-In or Producing) Initial PSI: Tubing 60 Intermediate 1A Casing 56 Bradenhead -2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME					
5 min	0		56		
10 min	0		55		
15 min	0		55		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	/
Nothing	
Gas	/
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 1A

REMARKS:

Puff when opened. Nothing when opened
after 5 min shut in

By David Hunter
Contractor
(Position)

Witness Monica Cuchling

E-mail address j.hunter@cottanwoodconsulting.com