



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

corrected

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 3-5-18 Operator ENDURING RESOURCES API #30-045-30605

Property Name BLANCO Well No. 43 Location: Unit Section 12 Township 27N Range 9W

Well Status (Shut-In or Producing) Initial PSI: Tubing 270 Intermediate N/A Casing 270 Bradenhead 15

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM		
	BH	Int	Csg	Int	Csg	
TIME						
5 min	0		270			
10 min	0		270			
15 min	0		270			
20 min	0		270			
25 min	0		270			
30 min	0		270			

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges <u>✓</u>	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water <u>✓</u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ✓ FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 w/ drip INTERMEDIATE N/A

REMARKS:

WATER FLOW AT 2 min 20 sec (FAST TO SLOW DRIP)

10.5 in AT START (CRACK IN DRAIN LINE HAD TO USE BUCKET)

2.5 GAL AT FINISH

WITNESSED BY MONICA

By [Signature]

Witness

AIR QUALITY SPECIALIST
(Position)

E-mail address sb@emh enduringresources.com

NMOC

MAR 22 2018

DISTRICT III