



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT (TA OR UIC)

Date of Test 4-10-2018 Operator Hilcorp Energy Co. API # 30-0 39-26528

Property Name San Juan 27-5 Unit Well # 40F Location: Unit N Sec 16 Twn 27 Rge 5

Land Type:

State X
Federal _____
Private _____
Indian _____

NMOC
APR 11 2018
DISTRICT III

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas X
Pressure observation _____

Temporarily Abandoned Well (~~TA~~) Post Workover TA Expires:

Casing Pres. Ø
Bradenhead Pres. Ø
Tubing Pres. Ø
Int. Casing Pres. _____

Tbg. SI Pres. _____
Tbg. Inj. Pres. _____

Max. Inj. Pres. _____

Pressured annulus up to 575 psi. for 30 mins. Test passed/failed

REMARKS: Pressured up to 575psi - Holding at 575psi at 15 min. Held for
whole test at 575psi.

hole 4570' CR 4750'
By [Signature]
(Operator Representative)

Well depth 1000# spring 1hr shut/inlet last Cal 4-3-18
Witness [Signature]
(NMOC)

Onsite Super
(Position)

Revised 02-11-02