



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4.23.18 Operator Hilcorp Energy Co. API #30-0 45-0714
Property Name Hubbell STC Well No. 2 Location: Unit 30 Township 28 Range 10
Well Status (Shut-In or Producing) Initial PSI: Tubing 10 Intermediate N/A Casing 11 Bradenhead 2.7

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		10		
10 min	0		10		
15 min	0		10		
20 min	0		10		
25 min	0		10		
30 min	0		11		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>✓</u>	
Surges	
Down to Nothing	
Nothing	
Gas <u>✓</u>	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

5 min - fumes - 10 - 15 - 20 - 25 - 30
Down to fumes at 12 seconds - down to nothing
at 5 min shut-in

By Ala [Signature]

Witness Monica [Signature]

(Position)

E-mail address _____

Try for a Gas analysis
all things.