NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3district.htm

DISTRICT III
APR 30 2018
NMOCD

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-30-18 Operator Hilcorp API #30-0 45-22533

Property Name Hancock Com Well No. 1A Location: Unit ___ Section 1 Township 31 Range 13

Well Status (Shut-In or Producing) Initial PSI: Tubing 54 Intermediate N/A Casing 56 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead BH	Bradenhead Int	Bradenhead Csg	INTERM Int	INTERM Csg
TIME 5 min	0		56		
10 min	0		57		
15 min	0		57		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	✓	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR_____ FRESH_____ SALTY_____ SULFUR_____ BLACK_____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS: Nothing when opened. Nothing when opened after 5 min shut in

By Doug O'Dell
Pumper
(Position)

Witness Monica Kuehling

E-mail address _____