



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

NMOCd

APR 26 2018

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-26-18 Operator Synergy OP API #30-0 45-33469

Property Name Madrid 29-13-6 Well No. 111 Location: Unit 3 Section 6 Township 29 Range 13

Well Status (Shut-In or Producing) Initial PSI: Tubing 28 Intermediate Casing 28 Bradenhead 1.5

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>26</u>		
10 min	<u>0</u>		<u>26</u>		
15 min	<u>0</u>		<u>26</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	<u>/</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 1.1

INTERMEDIATE N/A

REMARKS:

Bad pump bad tubing - long puff to dead when
opened - nothing when opened after 5 min shut in

By Daniel L. B...
LEASE OPERATOR
(Position)

Witness Monica Kuehling

E-mail address