



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distrct.htm](http://emnrd.state.nm.us/ocd/District%20III/3distrct.htm)

NMOCd
APR 26 2018
DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-26-18 Operator Synrg API #30-0 45-33470
Property Name Machid 2943-6 Well No. 112 Location: Unit C Section 6 Township 29 Range 13
Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 27 Intermediate 1/A Casing 27 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>27</u>		
10 min	<u>0</u>		<u>27</u>		
15 min	<u>0</u>		<u>27</u>		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	<u>✓</u>	
Nothing		
Gas	<u>✓</u>	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 1/A

REMARKS:

Hole tubing producing without pumping
Puff when opened. Nothing when opened after
5 min shut in

By Daniel J. Byrd
LEASE OPERATOR
(Position)

Witness Mona Kucharsky

E-mail address _____