		Sug billingen at						
3		RECE	IVED					
Form 3160-5 (August 2007)	UNITED STATI DEPARTMENT OF THE BUREAU OF LAND MAN	INTERIORAPH 2	Expires: July 31, 2010					
		Farmington I	Field Offic	5. Lease Serial No.	ISF-080516A			
SU	NDRY NOTICES AND REPO							
	se this form for proposals t d well. Use Form 3160-3 (A							
	UBMIT IN TRIPLICATE - Other inst		7. If Unit of CA/Agreement,					
1. Type of Well Oil Well	X Gas Well Other		8. Well Name and No.	1 Juan 28-5 Unit				
				San Juan 28-5 Unit 57				
2. Name of Operator	Hilcorp Energy Compa	nv	9. API Well No. <b>30-039-07393</b>					
3a. Address	3b. Phone No. (include area		10. Field and Pool or Explora	and Pool or Exploratory Area				
PO Box 4700, Farming		505-599-340	00	Basin Dakota				
4. Location of Well (Footage, Sec., T Surface Unit A (	NENE), 890' FNL & 1150' FE	L, Sec. 19, T28N, R	05W	11. Country or Parish, State Rio Arriba	, New Mexi	co		
12. CHECK	THE APPROPRIATE BOX(ES)	TO INDICATE NATUR	E OF NOT	TICE, REPORT OR OTH	IER DATA			
TYPE OF SUBMISSION		TYP	E OF AC	TION				
Notice of Intent	Acidize	Deepen		roduction (Start/Resume)	Water Shut-C			
V. C. Issuer Denset	Alter Casing	Fracture Treat		eclamation	Well Integrity	1		
X Subsequent Report	Casing Repair Change Plans	New Construction Plug and Abandon		ecomplete emporarily Abandon	X Other	clamation		
Final Abandonment Notice	Convert to Injection	Plug Back		/ater Disposal				
-	or final inspection.) P&A'd on 10/20/97. Final rec le reclamation work was ins	-		-		; now		
14. I hereby certify that the foregoing	is true and correct. Name (Printed/Type	ed)						
Etta Trujillo		Title Ope	rations/R	egulatory Technician S	ðr			
Signature	Fit	Date	4/19/201	18				
	THIS SPACE FO	R FEDERAL OR ST						
Approved by	epted for Record		Tial		APR	26	201	
Conditions of approval, if any, are atta	ached. Approval of this notice does not	warrant or certify	Title		Date		_	
entitle the applicant to conduct operat			Office	AOCD				
	e 43 U.S.C. Section 1212, make it a crim ts or representations as to any matter wit		and willfully	to make to any department of	agency of the United	States any	Ý	
(Instruction on page 2)								

API#: 30-039-07393		Location Name: SAN JUAN 28-5 57 UL-Sec-TWN-Rng: A T22N K5W Sec 19			Date: 3-21-2018 Revision 2 (3/7/17) Lat/Long: 36,65(535, ~107,394852				
Surface Owner: BLM		Lease#			Lat/Long: 36.651535, -107.394852 County/State: RID ALRIBA HM				
Pipeline Owner: HILOLP				Twin/Co-Locate Well Name & Operator:					
	Age	ency	Insp	Contractory			Seed Mix:		
- Ma valuer		da	100	p show at				-	0
Interim Reclamation	Completed	Incomplete	NIA	Final Reclamation	Completed	NIA	Remediation	Completed	Incomplete
lave pit sample results been approved		-		3rd party pipeline removed	V		Facilities stripped		+
las water been removed from pit				Anchors removed	10		Certificate of waste Issued & approved		-
lave pit marker photos been taken				Equipment and piping removed	10		Depth:		
las certificate of waste been issued & approved				Power poles removed		1-	Width:		-
lave all pit contents been removed				Cathodic protection removed	10		Length:		-
las sample after content removal been taken		-		Vegetative cages removed	10		Date of Excavation Start:		-
s location contoured				CMP's removed	1		Date of Excavation End:		
s there 4' of cover over pit				Non native gravel buried or removed	V		Date of Backfill Start:		
as top soil been spread evenly				Noxious weeds removed or sprayed	V		Date of Backfill End:		
as all non-native gravel been buried or removed	-	-		Insvasive weeds removed or sprayed	V		Yards Hauled Out:	-	-
las pit liner been removed	-	-		Contouring complete	-	-	Impacted Soil Hauled To:		-
las all trash been removed	-			Top soil spread	1	-	Yards Hauled In:		
fave all weeds been removed				Diversions clean and functional	1		Fresh Soll Hauled in From:	$\vdash$	
eardrop allows vehicle access to all facilities	-			Silt trap clean and functional	K		Approval to backfill	$\vdash$	-
Drainage ditches allow adequate run off				Cattle guard / gates removed		10	Back fill mechanically compacted	$\vdash$	+
All non-traffic areas disked properly	-			Cellar / mouse hole covered		K	Facilities reset	$\vdash$	-
	-			Erosion under control	K		Trash and debri removed		
All non-traffic areas seeded				and sender services and sender services and services	K				
Seeded areas have been mulched	-			Location property ripped	10		Close Out Completed		_
Noxious weeds have been removed or sprayed				Location properly disked	K	_	Soli Removal Sundry Ready to be Filed		
nvasive weeds have been removed or sprayed				Location seeded		_			
Barriers set to deter traffic				Photo transect installed		11			
Slit traps are functional				Access road properly closed	V				
Culverts are functional				Public use controlled	10				-
Jpper diversion is functional	-	-		Barriers in place	V	-			-+
lave wellhead cages and jersey barriers been removed		-		Grazing controlled					-+
	-			P&A marker Installed & legible	K		-		-
Have reclamation pictures been taken Growth at least 70%	-		$\vdash$	Well sign removed	K				
	-			The second s	M				_
Agency Inspection Date;				Growth at least 70%	1				
Sundry is ready to file				Trash and debris removed from location	N				
		-		Final reclamation photos taken	V				
				Agency Inspection Date: 3-21-2018					
				FAN Ready to be filed		2			-
Comments:				Comments:		Man Land	Comments:		
-				POST FENAL INSPECTION					