



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/District.htm](http://emnr.state.nm.us/ocd/District%20III/District.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-4-18 Operator Hilcorp Energy API #30-0 45-07112
Property Name Order 17 Well No. 3 Location: Unit M Section 26 Township 28 Range 10
Well Status (Shut-In or Producing) Initial PSI: Tubing 163 Intermediate N/A Casing 7 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>4</u>		
10 min	<u>0</u>		<u>5</u>		
15 min	<u>0</u>		<u>4</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>/</u>
Nothing	
Gas	<u>/</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Well sign illegible on facts- need new sign- long
Duff when opened- Casing dropped when bh opened.
Nothing when opened after 5 min shut in

By Joey Coufal
Joey Coufal
(Position) MSO

Witness Monica Tuckling

E-mail address _____